

Inspection Photos
Location Name: Johnsons Corner 35 F Pad
Location ID: 440793



Location entrance



Wellheads



Inspection Photos
Location Name: Johnsons Corner 35 F Pad
Location ID: 440793



Dead trees



Lube oil tank wildlife netting

Inspection Photos
Location Name: Johnsons Corner 35 F Pad
Location ID: 440793



North crude oil tank placards



North crude oil tank placards

Inspection Photos
Location Name: Johnsons Corner 35 F Pad
Location ID: 440793



North produced water tank placards



Maintenance tank placards