

Inspection Photos
Long Ridge J15
Spill/Release ID: 474500
Inspection Date: March 31, 2020 & April 1, 2020



3/31/2020 Ground surface where pipeline fluids daylighted (north side of the excavation).



3/31/2020 Excavation looking north.



Inspection Photos
Long Ridge J15
Spill/Release ID: 474500
Inspection Date: March 31, 2020 & April 1, 2020



3/31/2020 Southern extent of the excavation.



3/31/2020 Excavation looking west.



Inspection Photos
Long Ridge J15
Spill/Release ID: 474500
Inspection Date: March 31, 2020 & April 1, 2020



4/1/2020 Excavation looking east, the 10-inch pipeline is on the right and the 8-inch pipeline is on the left.



4/1/2020 Excavation looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Long Ridge J15
Spill/Release ID: 474500
Inspection Date: March 31, 2020 & April 1, 2020



4/1/2020 Stockpiled soil on the J15 location.



Excavation area looking east.



Inspection Photos
Long Ridge J15
Spill/Release ID: 474500
Inspection Date: March 31, 2020 & April 1, 2020



4/1/2020 Excavation looking southeast



4/1/2020 Stockpiled material on the west side of the excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources