

Inspection Photos  
Location Name: HSR Church 14-17  
Location ID: 329979



Photo 1 WH sign

Photo 2 WH

**Inspection Photos**  
**Location Name: HSR Church 14-17**  
**Location ID: 329979**



**Photo 3 Horizontal Heated Separator**

**Photo 4 Gas meter Run No test card inside meter house**

Inspection Photos  
Location Name: HSR Church 14-17  
Location ID: 329979



Photo 5 TB