

Inspection Photos

Location Name: LARAMIE ENERGY LLC Winter Flats /1-2-100 Pad

Location ID: 312565



Photo #0912 from entrance to location



Photo #0913 Unused hose in tank containment.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Winter Flats /1-2-100 Pad

Location ID: 312565



Photo #0914 Tank containment liner in need of maintenance.