

# Final Reclamation Inspection

April 6, 2020

Operator: FOUNTAINHEAD RESOURCES LTD - #30658

API #: 05-123-11903

Inspection Document #: 697501285

Weld County, CO

NWSW Section 5 T5N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: LITTLE WILL #11  
API #: 05-123-11903



**Photo 1.** Google Earth aerial imagery taken 8/18/2012 during active operations illustrates the disturbance areas.

Inspection Photos  
Location Name: LITTLE WILL #11  
API #: 05-123-11903



**Photo 2.** Photo taken from the eastern disturbance, facing West. Photo illustrates the establishment of Winter wheat. Disturbance areas appear reflective of reference crop areas.

Inspection Photos  
Location Name: LITTLE WILL #11  
API #: 05-123-11903



**Photo 3.** Photo taken from the eastern access road, facing North. Photo illustrates the disturbance area to the left of the red-dashed line and reference crop area to the right.

Inspection Photos  
Location Name: LITTLE WILL #11  
API #: 05-123-11903



**Photo 4.** Photo taken from the central disturbance area, facing East. See comments under Photos 2 and 3.

Inspection Photos  
Location Name: LITTLE WILL #11  
API #: 05-123-11903



**Photo 5.** Reference photo taken west of the disturbance area, facing North. See comments under Photos 2 and 3.