



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Appears to be plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.295560,-104.546670
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		
Comment:	Shares containment with crude oil tank.				Date:
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 244033 Type: WELL API Number: 123-11826 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, has yellow "LTSI" variance tag.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418914 Type: WELL API Number: 123-32067 Status: AL Insp. Status: AL

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: AL

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418917 Type: WELL API Number: 123-32068 Status: AL Insp. Status: AL

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: AL

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 4/7/20 at approximately 0718 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Thoutt 2 of Noble Energy at API# 05-123-11826 in Weld County, Colorado.                      While there, I observed a production well that is SI, has yellow "LTSI" variance tag. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report. Continuing education inspections</p>	burnsa	04/07/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101427	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117429">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117429</a>