

Construction and Stormwater Inspection

April 6, 2020

Operator: NGL WATER SOLUTIONS DJ LLC- #10373

Location ID: 450612

Inspection Document #: 697501289

Weld County, CO

SWNW Section 35 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NGL #C10B
Location ID: 450612



Photo 1. Photo taken from the southeastern proposed location, facing Northeast. Photo illustrates no construction activities have commenced. Location stakes were observed and equipment staged at location.

Inspection Photos
Location Name: NGL #C10B
Location ID: 450612



Photo 2. Photo taken from the southeastern proposed location, facing West. See comments under Photo 1.