

# *Inspection Photos*

*Loc#335194*

*Operator: Terra*

*Inspection #: 692402062*

*Inspection Date: 3/27/20*





Photo#1:  
Overview of Location to Northwest.

March 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335194



Photo#2:  
View of Interim Reclamation area.

March 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335194



Photo#3:  
Stormwater concerns.



Photo#4:  
Stormwater concerns.

March 25, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Langstaff RMV Loc#335188