

# *Inspection Photos*

*Loc#335614*

*Operator: Terra*

*Inspection #: 692402066*

*Inspection Date: 3/27/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southeast.

March 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335614



Photo#2:  
View over Interim Reclamation to Northwest.

March 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335614





Photo#3:  
Blocked entry looking out of Location



Photo#4:  
Blocked entry looking into Location.

March 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335614