

Inspection Photos

API: 071-09132

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/6/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 4/6/2020

Inspection Photos



Photo 1. Facing northwest along the main lease road toward the location. The road has been graded since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 4/6/2020

Inspection Photos



Photo 2. Facing northwest along the main lease road toward the location. The road has graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 4/6/2020

Inspection Photos



Photo 3. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 4/6/2020