

Inspection Photos

API: 071-08321

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/6/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/6/2020

Inspection Photos



Photo 1. Facing west along the main lease road in Alamosito Canyon. The road has been graded to the location since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/6/2020

Inspection Photos



Photo 2. Facing southwest toward the access road. The access road has been graded to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/6/2020

Inspection Photos



Photo 3. Facing back toward the access road from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/6/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/6/2020