

# Inspection Photos

4/06/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 439135

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 439135



**Photo 1:** Photo of the 5 active wells on the Location.



**Photo 2:** Photo taken from the eastern end of the Location, facing north. Photo shows recent reclamation activities appear to have been conducted on the Location; soils appear to have been recently replaced, contoured, and slopes have been stabilized with a hydromulch.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 439135



**Photo 3:** Continued from photo 2. Photo shows hydromulch appears to have been applied to the slopes of the Location, and the interim areas.



**Photo 4:** Photo taken from the western end of the Location, facing north; Photo shows interim reclamation in process.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 439135



**Photo 5:** Photo taken from the western end of the Location, facing north; Photo shows interim reclamation in process.



**Photo 6:** Photo taken from northern corner of the Location; Photo shows unused rock-socks being stored on the Location.

