

Inspection Photos

Loc#335638

Operator: Terra

Inspection #: 692402068

Inspection Date: 3/27/20





Photo#1:
Overview of Location to Northeast.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335638



Photo#2:
BMP at SW corner.



Photo#3:
BMP at SW corner.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335614



Photo#4:
Failed BMP.



Photo#5:
Failed BMP.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335614



Photo#6:
Failed BMP.




Photo#7:
Failed BMP.

March 27, 2020



Photo#8:
Noxious weed, Tamarisk.



Photo#9:
Noxious weed, Tamarisk.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335614



Photo#10:
Unknown deposit along West side of site.



Photo#11:
Unknown deposit along West side of site.

March 27, 2020