

Inspection Photos
Location Name: UPRR 43 Pan AM B #3
Location ID: 318639



Photo 1 WH and sign



Photo 2 No meter on electric panel and breaker in the off position. Pumping unit is not able to operate with out power.