

Inspection Photos

Operator: Catamount Energy
API#: 067-09389
Date: 4/8/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Vegetation is progressing with a mixture of grasses such as western wheatgrass, smooth brome, crested wheatgrass, and sand dropseed.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photos 4/5. View of musk thistles within the project area.



Photo 6. View of reference area vegetation, comprised of sagebrush shrubland with understory of grasses and forbs such as blue grama and sand dropseed.