

# Inspection Photos

API: 071-07542

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/9/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07542 | Date: 4/9/2020

## Inspection Photos



**Photo 1.** Facing toward the pit at the location. Water level in pit is above freeboard.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07542 | Date: 4/9/2020

## Inspection Photos



**Photo 2.** Water level in the pit is above the freeboard marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07542 | Date: 4/9/2020



## Inspection Photos



**Photo 3.** Well sign is posted at the meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07542 | Date: 4/9/2020

## Inspection Photos



**Photo 4.** Facing northwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07542 | Date: 4/9/2020