

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 1: Tank Battery Sign



Photo 2: Tank Battery



Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 3: Pumpjack



Photo 4: Stained soil



Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 5: Stained soil



Photo 6: Weeds removed



Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 7: Weeds removed



Photo 8: Weeds removed



Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 9: Trash/unused equipment




Photo 10: Trash/stained soil removed

