

Inspection Photos
Location Name: Schug Harland K 1
Location ID:319991



Pic 1



Pic 2 leaking wellhead

Inspection Photos
Location Name: Schug Harland K 1
Location ID:319991



Pic 3



Pic 4 leaking wellhead

Inspection Photos
Location Name: Schug Harland K 1
Location ID:319991



Pic 5



Pic 6

Inspection Photos
Location Name: Schug Harland K 1
Location ID:319991



Pic 7



Pic 8

Inspection Photos
Location Name: Schug Harland K 1
Location ID:319991



Pic 9 oil in pit



Pic 10

Inspection Photos
Location Name: Schug Harland K 1
Location ID:319991



Pic 11



Pic 12 oil in pit