

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2020

Submitted Date:

04/10/2020

Document Number:

695102532**FIELD INSPECTION FORM**Loc ID 308306 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10351Name of Operator: WAPITI OPERATING LLCAddress: 1310 W SAM HOUSTON PKWY NCity: HOUSTON State: TX Zip: 77043**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	Production superintendent
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist
Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com	Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265685	WELL	PR	05/01/2014	GW	071-07795	VPR C 115	PR

General Comment:

Inspected FacilitiesFacility ID: 265685 Type: WELL API Number: 071-07795 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

THIS IS A FOLLOWUP TO INSPECTION DOC#695100383. CA APPROVED BASED ON PHOTOS SUBMITTED BY OPERATOR ON FIRR DOC#402006050.

beardslt

04/10/2020