

Inspection Photos
Location Name: McCallum Unit 95
Location ID: 324648



Photo 1. Stained soil at wellhead.



Photo 2. Wellhead.

