

Inspection Photos
Location Name: Conoco Federal 34-1
Location ID: 324670



Photo 1. Overview of location taken facing west.

Inspection Photos
Location Name: Conoco Federal 34-1
Location ID: 324670



Photo 2. Apparent spill path. Photo taken standing on access road facing north.



Photo 3. Close-up of photo 2.



Inspection Photos
Location Name: Conoco Federal 34-1
Location ID: 324670



Photo 4. Product in apparent spill path.



Photo 5. Apparent tilling in apparent spill path.



Inspection Photos
Location Name: Conoco Federal 34-1
Location ID: 324670



Photo 6. Product and tilling in apparent spill path.



Photo7. Product in apparent spill path.

Inspection Photos
Location Name: Conoco Federal 34-1
Location ID: 324670



Photo 8. Photo looking towards wellhead from apparent terminus of spill pathway.



Photo 9. Looking towards access road from bottom of drainage.



Inspection Photos
Location Name: Conoco Federal 34-1
Location ID: 324670



Photo 10. Looking towards apparent origin point of spill towards well.



Photo 11. Looking towards apparent terminus in drainage bottom from apparent origin.

