

Inspection Photos

4/09/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335190

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335190



Photo 1: Photo taken from the active wells on the Location, facing north.



Photo 2: Photo taken from the northeast end of the Location, facing southwest. Photos 2-4 provide an overview of the Location from southwest, west, to northwest.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335190



Photo 3: See comments under photo 2.



Photo 4: See comments under photo 2.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335190



Photo 5: See comments under photo 2. Photo also shows large areas of cut slope that are exposed and at risk of erosion degradation.



Photo 6: Photo taken from the cut slopes on the southeast end of the Location. Photo shows erosion netting; Netting shows signs of disrepair; Maintenance advised.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335190



Photo 7: Photo taken from the south end of the Location, facing south. Photo shows tank and interim areas.



Photo 8: Photo taken from the west end of the location, facing northwest. Photo shows interim areas and slopes.