

Inspection Photos
Location Name: Nickerson #4
Location ID: 326976



Photo 1 – Trash on the Northeast side of Pumping Unit



Photo 2 – Unused Propane Tank, Pumping Unit, Engine and Engine Housing

Inspection Photos
Location Name: Nickerson #4
Location ID: 326976



Photo 3 – Stained Soil at Engine




Photo 4 – Unmarked Riser. Well has been Cut and Capped

Inspection Photos
Location Name: Nickerson #4
Location ID: 326976



Photo 5 – Unused Chemical Tanks and Containers




Photo 6 – Unused Separator and Stack

Inspection Photos
Location Name: Nickerson #4
Location ID: 326976




Photo 7 – Unused Crude Oil Tank and Stairs



Photo 8 – Unmarked Riser at Crude Oil Tank

Inspection Photos
Location Name: Nickerson #4
Location ID: 326976



Photo 9 – Gaps under Mesh Netting