

Pit Status Evaluation Form

Pit Overview:

| | |
|--|-------------------------------|
| Pit Name: ALBERT SACK "F" | Facility ID: 118729 |
| Current Status: Unknown | Status Date: 9/23/1999 |
| Current Operator: AMOCO PRODUCTION COMPANY / 2500 | |
| Updated Operator: | |
| Form 15 Pit Permit Doc #: | Permit Date: |
| Related Facilities: A F SACK #1 (API 05-123-15184; Facility ID 247387; Loc ID 327813) | |

| | | | |
|---|-------------------|--------------------|-----------------|
| County: WELD | | | |
| Township: 1N | Range: 67W | Section: 31 | QQ: NESE |
| Original Latitude/ Longitude: 40.005808 / -104.930823 | | | |
| Updated Latitude/ Longitude: 40.005177 / -104.927627 | | | |
| Basis for Location Change: | | | |
| Corrected QQ based on field inspection letter (doc #383033) and pit inventory; lat/long corrected to TB | | | |

Pit Inspection/Information Request:

| | |
|---|--------------------|
| Field Inspection Date: | Document #: |
| Pit Still Present in Field: No | |
| Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below) | |
| Inspection Notes: | |
| | |
| Operator Required to Submit Form: NA | Due Date: |
| Form Request Sent To: | Sent Date: |

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 55305 | Date: 9/30/1991 |
| | Doc #: 200237563 | Date: 1/29/2010 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2142986 | Date: 8/21/1997 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location.

Pit Status Review Summary:

Based on records review and historic aerial imagery, there is no evidence that there was a pit on location; 1997 pit inventory report documents a fiberglass tank on location. Associated well PA 2/6/2017. Pit Status has been changed to closed.

