

Final Reclamation Inspection

April 6, 2020

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 425082

Inspection Document #: 697501294

Weld County, CO

NWSW Section 26 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SRC Leffler /26B
Location ID: 425082



Photo 1. Photo taken from the well location, facing North. Photo illustrates all surface equipment has been removed. However, Operator has failed to perform all final reclamation activities (i.e., contoured, seed, etc..).

Inspection Photos
Location Name: SRC Leffler /26B
Location ID: 425082



Photo 2. Photo taken from the well location, facing West. Photo illustrates gravel has been stored but has not been removed from location.

Inspection Photos
Location Name: SRC Leffler /26B
Location ID: 425082



Photo 3. Photo taken from the well location, facing South. See comments from Photo 1 and 2.

Inspection Photos
Location Name: SRC Leffler /26B
Location ID: 425082



Photo 4. Photo taken from the well location, facing East. See comments from Photo 1 and 2.

Inspection Photos
Location Name: SRC Leffler /26B
Location ID: 425082



Photo 5. Reference photo taken north of the well location, facing Northwest.