



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 9, 2020 3:45:40 PM MDT
Server Receive Date:	Apr 9, 2020 3:46:43 PM MDT
Reference Number:	20200409-18138872521
Location:	Unnamed Road, Durango, CO 81303, USA Apr 9, 2020 3:42:19 PM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 3, 2020
Well Name	SHORT, ORAN W, A 1
API Number	50670712800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Clean Up Land Owner Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up stained soil.

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



Completed work description of corrective action 3

Photo of fourth corrective action completed



Completed work description

Completed work description of corrective action 4

Summary of all work completed

Marked rig anchors.

Water tank capacity is on current sign.

New sign on equipment.

Cleaned up trash.

Cleaned up trash , installed new well equipment sign, marked rig anchors and cleaned up stains around equipment.