



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 10, 2020 4:53:24 PM MDT
Server Receive Date:	Apr 10, 2020 4:53:49 PM MDT
Reference Number:	20200410-18138953043
Location:	11501 CO-151, Ignacio, CO 81137, USA Apr 10, 2020 4:47:55 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 10, 2020
Well Name	TUBBS GAS UNIT 32-6-9 B 4
API Number	50670992700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Clean Up Contaminated Soils Grading of Well Pad

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Cleaned soil and installed muffler box

Completed work description of corrective action 2

Photo of third corrective action completed



Graded well pad

Completed work description of corrective action 3

Photo of fourth corrective action completed



Picked up old wattles

Completed work description of corrective action 4

Summary of all work completed

Picked up trash

Cleaned up stains, installed muffler box, graded location and picked up trash the pump Jack was not on site.