



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Cole Nichols (colen@horizonenvservices.com) |
| Submission Date: | Apr 13, 2020 9:43:46 AM MDT |
| Server Receive Date: | Apr 13, 2020 9:46:54 AM MDT |
| Reference Number: | 20200413-18139197356 |
| Location: | 557 Airpark Dr, Durango, CO 81303, USA Apr 13, 2020 9:43:00 AM MDT [View Map] |

Information

| | |
|-----------------|--|
| Name | colen@horizonenvservices.com |
| Date | Apr 10, 2020 |
| Well Name | SPANISH FORK GAS UNIT B 1 |
| API Number | 50670703700 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Clean up Operator Debris Clean Up Weed Debris |

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before mowing

Photo of third corrective action completed



Completed work description of corrective action 3

after mowing

Photo of fourth corrective action completed



Completed work description

pipe before removal

Completed work description of corrective action 4

mowed weed debris and removed piping

Additional photos



Completed work description

mowed weed debris and removed piping

Summary of all work completed

previous treatment dates 6/17/16, 8/1/17, 7/3/18 and 6/12/19