

Inspection Photos
Location Name: Colorado Federal 1
Location ID: 318901



Photo 1 – Tank Battery, weeds cut



Photo 2 – Pumping Unit, trash removed

Inspection Photos
Location Name: Colorado Federal 1
Location ID: 318901



Photo 3 – Well has been Plugged and Abandoned. Open Well Bore has been covered at Surface



Photo 4 – Weeds cut at Tank Battery

Inspection Photos
Location Name: Colorado Federal 1
Location ID: 318901



Photo 5 – Trash and Debris has been removed from Engine House