

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 1 – Tank Battery, weeds cut, Unused Equipment remains



Photo 2 – Well Bore has been covered at Surface

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 3 – Unused Pumping Unit, Engine and Housing remain