

Inspection Photos
Location Name: Clifford R Haller 32-11#1
Location ID: 317153



Photo 1 WH propane tank connected to motor



Photo 2 TNK BTRY

Inspection Photos
Location Name: Clifford R Haller 32-11#1
Location ID: 317153



Photo 2 Separators and meter run