

Inspection Photos
Location Name: UPRR Pan AM 1 #24
Location ID: 318456



Photo 1 WH



Photo 2 Trash and Debris: Dead weeds around electric panel and piles of dead weeds and trash on location.