

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 1 – Tank Battery**




**Photo 2 – Pumping Unit**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 3 – Pit, Wildlife Netting has been installed**



**Photo 4 – Weeds in Pit Containment**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**




**Photo 5 – Produced Water Tank NFPA label has faded**




**Photo 6 – Stained Soil at NE Loadline**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 7 – Unmarked Risers and Stained Soil**




**Photo 8 – Stained Soil inside West Treater shed**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 9 – Stained Soil at Exhaust**



**Photo 10 – Stained Soil inside the Engine Shed**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 11 – Crude Oil Tanks now have the Capacity Label**



**Photo 12 – Crude Oil Tanks now have the Capacity Label**





**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 13 – Wildlife Screens have been installed to Heater Treater Stacks**



**Photo 14 – Chemical Tank at Pumping Unit now has labels**