



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

Figure Four 8610A J19 497 API: 05-045-05130
Inspection: 700400998



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator & meter building.

Figure Four 8610A J19 497 API: 05-045-05130
Inspection: 700400998



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

Figure Four 8610A J19 497 API: 05-045-05130
Inspection: 700400998



Caerus Piceance LLC

DOUBLE WILLOW UNIT

FIGURE FOUR 8610A J19 497

NE/NW/SE, SEC. 119, T4S, R97W

UNIT #COC-67498X LSE #COC-50268

API #05-045-05130-00

GARFIELD, COLORADO

EMERGENCY PH: # **1-800-791-7691**

EMERGENCIES

CALL 911

39.68662, -108.31836, 7385.7ft, 265°

04/13/2020 01:37:41 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Battery sign.

Figure Four 8610A J19 497 API: 05-045-05130
Inspection: 700400998