



39.69172, -108.31223, 7364.1ft, 8°  
04/13/2020 02:10:05 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Double Willow 8601D A19 497 API: 05-045-07218**  
**Inspection: 700401006**





39.69216, -108.31196, 7363.8ft, 356°  
04/13/2020 02:05:34 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well head.**

**Double Willow 8601D A19 497 API: 05-045-07218**  
**Inspection: 700401006**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Separator.**

Double Willow 8601D A19 497 API: 05-045-07218  
Inspection: 700401006





39.69252, -108.31196, 7367.3ft, 355°  
04/13/2020 02:06:20 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tank.**

Double Willow 8601D A19 497 API: 05-045-07218  
Inspection: 700401006



39.69178, -108.31206, 7374.4ft, 315°  
04/13/2020 02:09:33 PM



Lat. 39.69215697 Long. -108.3118801

8601D A19 497



Caerus Piceance LLC

DOUBLE WILLOW UNIT

DOUBLE WILLOW 8601D A19 497

NE/NE, SEC. 19, T4S, R97W

UNIT #COC-67498X LSE #COC-50268

API #05-045-07218-00

GARFIELD, COLORADO

EMERGENCIES

CALL 911

EMERGENCY PH: #1-800-791-7691

39.69208, -108.3117, 7428.9ft, 212°

04/13/2020 02:04:57 PM



COLORADO  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 6. Battery sign.

Double Willow 8601D A19 497 API: 05-045-07218  
Inspection: 700401006



39.6924, -108.31188, 7358.6ft, 19°  
04/13/2020 02:06:00 PM