



39.68127, -108.29665, 7446.7ft, 263°
04/13/2020 03:19:50 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Double Willow 8616C P20 497 API: 05-045-07208
Inspection: 700401018



39.68127, -108.29673, 7453 0ft, 212°
04/13/2020 03:19:33 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

Double Willow 8616C P20 497 API: 05-045-07208
Inspection: 700401018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

Double Willow 8616C P20 497 API: 05-045-07208
Inspection: 700401018



39.68105, -108.29705, 7460.1ft, 276°
04/13/2020 03:20:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

Double Willow 8616C P20 497 API: 05-045-07208
Inspection: 700401018