

Final Reclamation Inspection

April 8, 2020

Operator: PETROSHARE CORPORATION- 10454

Location ID: 320356

Inspection Document #: 697501312

Adams County, CO

NESE Section 3 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WEIGANDT #43-3
Location ID: 320356



Photo 1. Photo taken from the well and battery location, facing South. Photo illustrates location is within a proposed housing development area.

Inspection Photos
Location Name: WEIGANDT #43-3
Location ID: 320356



Photo 2. Photo taken from the well and battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: WEIGANDT #43-3
Location ID: 320356



Photo 3. Photo taken from the well and battery location, facing Northwest.
See comments under Photo 1.

Inspection Photos
Location Name: WEIGANDT #43-3
Location ID: 320356



Photo 4. Photo taken from the northwestern well and battery location, facing Northwest. Photo illustrates Operator has failed to remove all oil and gas equipment.

Inspection Photos
Location Name: WEIGANDT #43-3
Location ID: 320356



Photo 5. Photo taken north of the well and battery location, facing West. Photo illustrates the housing development stormwater area.

Inspection Photos
Location Name: WEIGANDT #43-3
Location ID: 320356



Photo 6. Photo taken south of the well and battery location from the northernmost housing development area.