

Final Reclamation Inspection

April 8, 2020

Operator: PETROSHARE CORPORATION- 10454

Location ID: 320332

Inspection Document #: 697501314

Adams County, CO

NWSE Section 4 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SELTZER G U #2-4
Location ID: 320332



Photo 1. Photo taken from the western well and battery location, facing East. Photo illustrates all surface equipment has been removed. Location has not been reclaimed. Annual, weedy vegetation consisting mostly of tumbleweeds.

Inspection Photos
Location Name: SELTZER G U #2-4
Location ID: 320332




Photo 2. Photo taken east of the well and battery location, facing West. Photo illustrates the well and battery location above the red-dashed line and the reference area below.