

Final Reclamation and Stormwater Inspection

April 8, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320481

Inspection Document #: 697501316

Adams County, CO

SENE Section 4 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SELTZER PP #4-8
Location ID: 320481




Photo 1. Photo taken from the well and tank battery location, facing North. Photo illustrates Operator has failed to remove all surface equipment.

Inspection Photos
Location Name: SELTZER PP #4-8
Location ID: 320481



Photo 2. Photo taken from the southwestern well and tank battery location, facing West. Photo illustrates Operator has performed final reclamation activities throughout all other disturbance areas with the evidence of germination.

Inspection Photos
Location Name: SELTZER PP #4-8
Location ID: 320481



Photo 3. Photo taken east of the well and tank battery location, facing South. Photo illustrates a pipeline has been recently installed which has used a portion of the original access road- see Photo 4.

Inspection Photos
Location Name: SELTZER PP #4-8
Location ID: 320481



Photo 4. Photo taken east of the well and tank battery location, facing East.
See comments under Photo 3.

Inspection Photos
Location Name: SELTZER PP #4-8
Location ID: 320481



Photo 5. Photo taken east of the well and tank battery location, facing North.
See comments under Photo 3.