

Final Reclamation and Stormwater Inspection

April 8, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320281

Inspection Document #: 697501318

Adams County, CO

NENE Section 4 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SELTZER #1-4
Location ID: 320281



Photo 1. Photo taken from the well location entrance, facing South. Photo illustrates Operator has failed to remove all gravel and perform reclamation per Rule 1004 standards.

Inspection Photos
Location Name: SELTZER #1-4
Location ID: 320281



Photo 2. Photo taken from the well location, facing South. Photo illustrates the well location is not reflective of reference area vegetation.

Inspection Photos
Location Name: SELTZER #1-4
Location ID: 320281



Photo 3. Photo taken from the well location entrance, facing East. Photo illustrates Operator has failed to reclaim the main access road.

Inspection Photos
Location Name: SELTZER #1-4
Location ID: 320281



Photo 4. Reference photo taken western of the well location, facing East. Photo illustrates vegetation consisting mostly of Crested wheatgrass with some smooth brome.

Inspection Photos
Location Name: SELTZER #1-4
Location ID: 320281



Photo 5. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates Operator has performed final reclamation activities with the evidence of drill rows and germination. However, not all equipment has been removed.

Inspection Photos
Location Name: SELTZER #1-4
Location ID: 320281



Photo 6. Photo taken from the western associated offsite tank battery location, facing Northwest. See comments under Photo 5.