

# Final Reclamation and Stormwater Inspection

April 8, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320412

Inspection Document #: 697501320

Adams County, CO

SWNE Section 4 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SELTZER PP #4-7  
Location ID: 320412



**Photo 1.** Photo taken from the well location access road, facing South. Photo illustrates Operator has failed to properly perform reclamation per Rule 1004 standards.

Inspection Photos  
Location Name: SELTZER PP #4-7  
Location ID: 320412



**Photo 2.** Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: SELTZER PP #4-7  
Location ID: 320412



**Photo 3.** Photo taken from a portion of the main access road, facing East. Photo illustrates Operator has failed to reclaim the main access road.

Inspection Photos  
Location Name: SELTZER PP #4-7  
Location ID: 320412



**Photo 4.** Reference photo taken western of the well location, facing East. Photo illustrates vegetation consisting mostly of Crested wheatgrass with some smooth brome.

Inspection Photos  
Location Name: SELTZER PP #4-7  
Location ID: 320412



**Photo 5.** Photo taken from the associated offsite tank battery location, facing West. Photo illustrates Operator has performed final reclamation activities with the evidence of drill rows and germination. However, not all equipment has been removed.

Inspection Photos  
Location Name: SELTZER PP #4-7  
Location ID: 320412



**Photo 6.** Photo taken from the western associated offsite tank battery location, facing Northwest. See comments under Photo 5.