

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402370143

Date Received:

04/14/2020

Spill report taken by:

Hughes, Jim

Spill/Release Point ID:

474977

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>BP AMERICA PRODUCTION COMPANY</u>	Operator No: <u>10000</u>	Phone Numbers
Address: <u>1199 MAIN AVENUE SUITE 101</u>		Phone: <u>(505) 330-9179</u>
City: <u>DURANGO</u>	State: <u>CO</u>	Mobile: <u>(505) 330-9179</u>
Zip: <u>81301</u>		Email: <u>steven.moskal@bpx.com</u>
Contact Person: <u>Steve Moskal</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402365707

Initial Report Date: 04/08/2020 Date of Discovery: 04/08/2020 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR SWNW SEC 32 TWP 33N RNG 6W MERIDIAN NLatitude: 37.063493 Longitude: -107.532312Municipality (if within municipal boundaries): _____ County: LA PLATA

Reference Location:

Facility Type: PIPELINE☐ Facility/Location ID No _____Spill/Release Point Name: Tiffany Gathering☐ Well API No. (Only if the reference facility is well) 05- -☒ No Existing Facility or Location ID No.

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=5 and <100Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0Specify: 50 bbls of produced water

Land Use:

Current Land Use: CROP LANDOther(Specify): Livestock grazingWeather Condition: 65F, clear, breezy.Surface Owner: FEEOther(Specify): Private

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Produced water released from a gathering system. Release point located in grazing pasture. Water released flowed accross pasture and potentially contacted agricultural wetland. Gathering system was isolated. Area fenced off to mitigate cattle access. No recovered water.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
4/8/2020	La Plata County	Courtney Roseberry	-	email notification

Was there a Grade 1 Gas Leak? Yes ☐ No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

Was there damage during excavation? Yes ☐ No ☒

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 04/14/2020		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	50	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: Approximately 50 bbls of produced water was released

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☒ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 300 Width of Impact (feet): 40

Depth of Impact (feet BGS): Depth of Impact (inches BGS):

How was extent determined?

Physically walked using high accuracy handheld GPS unit.

Soil/Geology Description:

Silty clay.

Depth to Groundwater (feet BGS) 75 Number Water Wells within 1/2 mile radius: 7

If less than 1 mile, distance in feet to nearest Water Well 450 None ☐ Surface Water 115 None ☐

☐ ☒

Wetlands	235	None	Springs		None
Livestock	275	None <input type="checkbox"/>	Occupied Building	845	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

Surface water located 115' upgradient of release point (irrigation canal). Produced water flowed into agricultural/irrigation created wetland that has no connectivity to a waterway or drainage (limited by highway 151). Cattle were not in the area of the release and BP installed temporary fencing to restrict livestock entry to the release area. Depth to water determined from approximate surface elevation of release point to depth of water found on water well permit DWR 193931. La Plata County and landowner & tenant were contacted and notified of the release on 4/8/2020.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Soil and water samples collected on 4/8/2020, pending results. Results will be shared once received.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Steve Moskal

Title: Enviro Coord Date: 04/14/2020 Email: steven.moskal@bpx.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402370143	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402370254	SITE MAP
402370723	FORM 19 SUBMITTED

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)