

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE

Location ID: 312658



Photo #0966 from entrance to location



Photo #0968 Weeds growing inside tank containment.