

Inspection Photos
Location Name: Parker No. 4-35
Location ID: 316192
Inspection Date: April 9, 2020



Location sign.



“Oil gator” placed around wellhead on top of impacted material.



Inspection Photos
Location Name: Parker No. 4-35
Location ID: 316192
Inspection Date: April 9, 2020



View of the White River located south of the wellhead.



View of the pit on location looking east.



Inspection Photos
Location Name: Parker No. 4-35
Location ID: 316192
Inspection Date: April 9, 2020



View of the pit on location looking west.

