

Inspection Photos

Location Name: TELNA 24-22 FOLLOWUP CA 5-14-20

API#: 05-071-07099

INSP. #: 695102



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: TELNA 24-22 FOLLOWUP CA 5-14-20
API#: 05-071-07099
INSP. #: 695102




PHOTO 3: GAS METER CAL. REPORT

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT ACCORDING TO RULE 603.f.
THIS IS SECOND NOTICE TO REMOVE THIS UNUSED
EQUIPMENT. CA DATE IMMEDIATELY.

Inspection Photos

Location Name: TELNA 24-22 FOLLOWUP CA 5-14-20

API#: 05-071-07099

INSP. #: 695102



**PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT ACCORDING TO RULE 603.f.
CA DATE 5-14-20**

**PHOTO 6: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT ACCORDING TO RULE 603.f.
CA DATE 5-14-20**

Inspection Photos

Location Name: TELNA 24-22 FOLLOWUP CA 5-14-20

API#: 05-071-07099

INSP. #: 695102



PHOTO 7: TRASH ON LOCATION. PICK UP ALL TRASH ON LOCATION ACCORDING TO RULE 603.f. CA DATE 5-14-20

PHOTO 8: GUYLINE MARKER IN DOWN. Install proper guy line markers per Rule 1003.a CA DATE 5-14-20.