

Inspection Photos
Location Name: Randall Creek 13-27H
Location ID: 424282



Photo 1 – Tank Battery



Photo 2 – Wellhead, Stained Soil removed

Inspection Photos
Location Name: Randall Creek 13-27H
Location ID: 424282



Photo 3 – NE Deadman Anchor has been marked