

**Inspection Photos**  
**Location Name: Susie 11-9**  
**Location ID: 318999**



**Photo 1 – Tank Battery**



**Photo 2 – Pumping Unit**

**Inspection Photos**  
**Location Name: Susie 11-9**  
**Location ID: 318999**



**Photo 3 – Stained Soil cleaned up**