

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 1: Wellhead Sign



Photo 2: Unused equipment



Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 3: Unused equipment



Photo 4: Wellhead Sign

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 5: Unused equipment



Photo 6: Wellhead Sign

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 7: Unused equipment



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 9: Unused equipment



Photo 10: Stained soil

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 11: Wellhead Sign



Photo 12: Unused equipment

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 13: Wellhead Sign



Photo 14: Unused equipment



Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 15: Wellhead Sign



Photo 16: Stained soil

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Colorado Oil and Gas Conservation Commission
40.48224, -104.83316, 1450.1m, 357°
Apr 14, 2020 14:05:59

Photo 17: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.48224, -104.8332, 1452.3m, 277°
Apr 14, 2020 14:06:15

Photo 18: Stained soil

Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071




Photo 19: Tank Battery Sign



Photo 20: Tank Battery



Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 21: Trash



Photo 22: Unused risers



Inspection Photos
Location Name: Rubyanna 13 Pad
Location ID: 436071



Photo 23: Unused riser/ disconnected gas meter



Photo 24: Unused equipment

