

Inspection Photos
Location Name: Shannon Roberts #3
Location ID: 321500



Photo 1 WH



Photo 2 Sep/meter run and produced water tank

Inspection Photos
Location Name: Shannon Roberts #3
Location ID: 321500



Photo 3 TNK BTRY DEAD weed and trash on location.



Photo 4 Mechanical issue and stained soil crude oil tank load line.

Inspection Photos
Location Name: Shannon Roberts #3
Location ID: 321500



Colorado Oil and Gas Conservation Commission
40.02786, -104.9672, 1555.4m
Apr 15, 2020 12:29:47

Photo 5 Dead weeds and trash on location.

