

Inspection Photos  
Location Name: Sheley 1  
Location ID: 318143



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Sheley 1  
Location ID: 318143



Photo 3 TB signs

Photo 4 TB

**Inspection Photos**  
**Location Name: Sheley 1**  
**Location ID: 318143**



**Photo 5 ECDs**

**Photo 6 Vertical separator**

**Inspection Photos**  
**Location Name: Sheley 1**  
**Location ID: 318143**



**Photo 7 Horizontal Heated Separators, Vertical Separators**

**Photo 8 Gas meter run**

# Inspection Photos

Location Name: Sheley 1  
Location ID: 318143



Photo 9 Card inside meter house